


[Our Company](#)
[Products & Services](#)
[Quality](#)
[Tools](#)
[Contact Us](#)

Search our site...

More in this section:

[Copper Alloys](#)
[Gage Conversion](#)
[Galvanic Corrosion](#)
[Periodic Table of Elements](#)
[Standard Drill Size](#)
[Tap Drill Size](#)

Gage Conversion

Sheet Metal Gage Conversion Chart (Inches)

Gage No.	Steel	Stainless Steel	Aluminum
7	0.179	—	—
8	0.164	0.172	—
9	0.15	0.156	—
10	0.135	0.141	—
11	0.12	0.125	—
12	0.105	0.109	—
13	0.09	0.094	0.072
14	0.075	0.078	0.064
15	0.067	0.07	0.057
16	0.06	0.063	0.051
17	0.054	0.056	0.045
18	0.048	0.05	0.04
19	0.042	0.044	0.036
20	0.036	0.038	0.032
21	0.033	0.034	0.028
22	0.03	0.031	0.025
23	0.027	0.028	0.023
24	0.024	0.025	0.02
25	0.021	0.022	0.018
26	0.018	0.019	0.017
27	0.016	0.017	0.014
28	0.015	0.016	—
29	0.014	0.014	—
30	0.012	0.013	—
31	—	0.011	—

American Wire Gage Sizes

AWG #	Decimal Size
0	0.3249
2	0.2576
4	0.2043
6	0.1620
8	0.1285
10	0.1019
12	0.0807
14	0.0642
16	0.0508
18	0.0402
20	0.0319
22	0.0252
24	0.0201
26	0.0157
28	0.0126
30	0.0098
32	0.0079
34	0.0063
36	0.0051
38	0.0039
40	0.0031

Request for Quote:

Name	
Email address	
Organization	Begin RFQ