

Retighten carburetor flange

At the first maintenance job,
then every 45 000 km/30 000 miles

Carburetor engines with
Stromberg or **Zenith** carburetors

- Retighten all fixing screws on the Stromberg carburetor and all fixing nuts on the Zenith carburetor.

Note: The fastening nuts of the flange of the Solex carburetor 4A1 on engine M 110 **are not** to be retightened.

